High Point Ridge access road

Condition stills from video — 2 October 2026

Exhibit for an updated Canyon Regional Water Authority (CRWA) letter. These pages record what is visible in one video. They are not a legal conclusion, a rainfall study, or a finding of fault.

Source (CONFIRMED)

Item	Value
File	20261002_134425.mp4 (Samsung camera filename)
Bytes	282,225,891
SHA-256	556ca8d8be8141364739443963a31846f558a56a308dd03c647284ddc340c3b6
Recorded	2026-10-02 ~1:44 PM CDT (filename 134425; metadata creation_time 2026-10-02T18:46:17Z = 1:46 PM CDT at file close)
Length	1 minute 50 seconds
Device	Samsung, Android 16, UTC offset −0500
GPS	None in the file
Stills from	0:28 through 1:05. Worst pooling about 0:32–0:38.

Location (assumption)

Michael Jon Long identifies this clip as the High Point Ridge access road serving 181 High Point Ridge, Seguin, TX 78155. The video file is not GPS-tagged.

Visible in the stills (CONFIRMED)

Overcast sky. Unpaved caliche/gravel traveled way. Standing muddy water pooled in depressions on that traveled way, especially 0:32–0:38. Rutted / water-cut edge at 0:32–0:34. A short paved curve meets the caliche at 0:28.

Not claimed from this video

Rainfall totals. Rain after 2 October 2026. Who maintains the road. Fault. Whether the road is impassable. Those stay out of this exhibit.

Prepared 31 October 2026 from the local file. Crops cut empty sky and the dashboard mount so the road fills the page. Full frames are in the same folder.

Still 1 — video time 0:28

Paved curve meeting unpaved caliche



The traveled way leaves a short paved curve and meets loose caliche/gravel. Overcast. Surface already wet at the edges.

Source: 20261002_134425.mp4 at 0:28. Crop of the phone frame. Location is assumed High Point Ridge (not GPS-tagged).

Still 2 — video time 0:32

Ruts and wet washboard at the edge



Unpaved surface with a rutted, water-cut edge. Standing moisture in the low spots. Fence and posted signs along the side.

Source: 20261002_134425.mp4 at 0:32. Crop of the phone frame. Location is assumed High Point Ridge (not GPS-tagged).

Still 3 — video time 0:34

Standing puddles and eroded shoulder



Pooled muddy water on the left of the traveled way. Eroded, rutted shoulder on the right. Loose caliche in this frame.

Source: 20261002_134425.mp4 at 0:34. Crop of the phone frame. Location is assumed High Point Ridge (not GPS-tagged).

Still 4 — video time 0:35

Standing water in the travel path



Several distinct pools of standing water sit in the traveled caliche. Wheel-path depressions are visible.

Source: 20261002_134425.mp4 at 0:35. Crop of the phone frame. Location is assumed High Point Ridge (not GPS-tagged).

Still 5 — video time 0:36

Pooled water across the traveled way



Multiple puddles span the width of the traveled way. Unpaved caliche/gravel with depressions holding water.

Source: 20261002_134425.mp4 at 0:36. Crop of the phone frame. Location is assumed High Point Ridge (not GPS-tagged).

Still 6 — video time 0:38

Wheel-path puddles continue



Standing water remains in the wheel paths as the vehicle continues. Same unpaved surface, overcast, wet.

Source: 20261002_134425.mp4 at 0:38. Crop of the phone frame. Location is assumed High Point Ridge (not GPS-tagged).

Still 7 — video time 1:05

Looking down the caliche — water still standing



Further along the same unpaved road. Standing water still visible in the traveled way. Blue dumpster is a landmark in this clip only.

Source: 20261002_134425.mp4 at 1:05. Crop of the phone frame. Location is assumed High Point Ridge (not GPS-tagged).